



ПОЗ	ОБОЗНАЧЕНИЕ	К-ВО
1	2-х коленка	4
2	Профиль 40x80 L=750	1
3	Сухарь 100	4
4	Заглушка 80x40	1
5	Винт вн.ш. М8 х 16	10
6	Основание	1
7	Винт М8 х 30 потай. DIN 965	2